To be Total

4 APR 1986

In Reply T-3-2 Refer to: R(86)E082

Mr. David L. Bauer Vice President, Environmental Affairs IT Corporation P.O. Box 2995 23456 Hawthorne Blvd. Torrance, CA 90509

Dear Mr. Bauer:

On February 20, 1986 a hazardous waste investigation was conducted at your Vine Hill, CA facility. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act of 1976. A copy of our investigation report is enclosed for your information.

EPA routinely provides copies of investigation reports to State agencies. Such releases will be handled according to the basic rules governing business confidentiality claims contained in the Code of Federal Regulations (40 CFR Part 2). Any claim of confidentiality should be made within fifteen (15) working days from the receipt of this letter. EPA will construe a failure to furnish timely comments as a waiver of the confidentiality claim.

If you have questions related directly to technical aspects of this report, please contact Barry Cofer at (415) 974-7844. Questions related to your interim status should be directed to the Berkeley office of the Department of Health Services at (415) 540-2043.

Sincerely yours,

ORIGINAL SIGNED BY:

Kathleen G. Shimmin Chief, Field Operations Branch

Enclosures

Cc: Caroline Cabias, DOHS-HQ (w/encl.)
Paul Smith, DOHS-HQ (w/o encl.)
Dwight Hoenig DOHS-Berkeley (w/encl.)

Roger Johnson, SWRCB (w/o encl.)	
Harold Singer, RWOCB (W GONEURRENCES	
SYMBOL 17-3-2 T3-2 T-3-2 T-3	
SURNAME & COFE BLOOD HORGAN Shimmin	
DATE 3/29/86 3/31/86 4/186 4/3/86	
EPA Form 1320-1 (12-70)	OFFICIAL FILE COPY

Inspection Report
U.S. Environmental Protection Agency
Region 9
Toxics and Waste Management Division
Field Operations Branch

Purpose: RCRA Investigation

Facility: IT Corp., Vine Hill Facility

896 Waterbird Way Martinez, CA 94553

EPA ID number: CAD000094771

Report number: R(86)E082

Date of Investigation: February 20, 1986

EPA Inspectors: Barry Cofer

Field Investigator

Tamara Brode

Environmental Engineer

Facility Representative: Micheal S. Foster

Program Manager, Environmental Affairs

G. Douglas Clark

Regional Director for Regional Compliance

Report Prepared By: Barry Cofer

Report Date: March 28, 1986

BACKGROUND

This inspection was conducted to determine how the facility was coping with the surface impoundment freeboard requirements. From 9.5" to 10" of rain had fallen in the six days preceding the inspection.

INVESTIGATION

The Vine Hill facility of IT Corporation was not accepting waste at the time of inspection. A portable pump was being utilized to equalize the ponds. Pond 101 had less than 24" freeboard unless the dike roadway crown was considered as the berm. See photographs, Attachment #1, pages 2-3. The former Acme Fill Corp. ponds were reportedly used for rainwater storage only.

POTENTIAL VIOLATION

40 CFR 265.222 (a): Facility did not maintain enough freeboard to prevent any overtopping of the dike by overfilling, wave action, or a storm.

ATTACHMENTS

1. Photographs



DATE: 2/20/86 NAME: BRODE
DESCRIPTION: POND 105 - CONTENTS
REING PUMPEN MA DIPELINE TO
TT-BAKER

DATE: 2/20/86 NAME: BROOKE DESCRIPTION: POND 101	





DATE: 2/20/86 NAME: COFER DESCRIPTION: SLUDGE IN	
DESCRIPTION: SCORE IN POND (0)	






DATE: 2/20/86 NAME: BRODE POND 101

DATE: 2/20/86 NAME: BRODE
DESCRIPTION: PORTABLE PUMP FOR
NOND EQUALIZATION





DATE: 2/20/86 NAME: BRODE DESCRIPTION: AND FORMERTY DUNED BY ACME FILE